



July 13, 2016

Environmental Protection Agency – Region 2
Division of Enforcement and Compliance Assistance – Air Compliance Branch
290 Broadway – 21st floor
New York, NY 10007-1866

Reference: Roebbling Building
 Clark & Elmer Streets
 Trenton NJ 08611

To Whom It May Concern:

The attached will serve as revision # 2 for the above reference project.
Should you have any questions or require additional information, please call this office.

Sincerely,


Nick Hoag
Project Manager

NK : pd

cc: File 70-15-042



July 13, 2016

New Jersey Dept of Health and Senior Services
Consumer and Environmental Health Services
135 East State Street
4th Floor
Trenton, NJ 08625-0369

Reference: Roebbling Building
 Clark & Elmer Streets
 Trenton NJ 08611

To Whom It May Concern:

The attached will serve as revision # 2 for the above reference project.
Should you have any questions or require additional information, please call this
office.

Sincerely,

A handwritten signature in blue ink, appearing to read "Nick Hoag" with a stylized flourish at the end.

Nick Hoag
Project Manager

NK : pd

cc: File 70-15-042



July 13, 2016

Department of Labor
Division of Public Safety & Occupational Safety & Health
Asbestos Control & Licensing Section
One John Fitch Plaza
Trenton NJ 08625-0949

Reference: Roebbling Building
 Clark & Elmer Streets
 Trenton NJ 08611

To Whom It May Concern:

The attached will serve as revision # 2 for the above reference project.
Should you have any questions or require additional information, please call this office.

Sincerely,


Nick Hoag
Project Manager

NK : pd

cc: File 70-15-042

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60-7 and 12:-120-7)

Date of Notification (1) 01/18/16 <small>Month/Day/Year</small>		Name of Building Owner/Operator (2) HHG Developmnet Associates LLC	
Agency Notified <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/> DEP <input checked="" type="checkbox"/> DCA <input checked="" type="checkbox"/> DOH	Type Notification	Street Address	
	Initial	165 Mercer Street	
	<input checked="" type="checkbox"/> Notification	City, State, Zip Code	
	<input checked="" type="checkbox"/> Amended	Trenton, NJ 08611	
	Notification	Name of Contact	Telephone Number
	Cancellation	David Henderson	609-392-4200

FACILITY INFORMATION

Name of Facility Where Abatement is Taking Place (3) Roebling Building			Type of Facility (4) <input type="checkbox"/> School (K12) <input type="checkbox"/> Subchapter 8 (Other than K12) <input checked="" type="checkbox"/> Other (i. e. Private & commercial buildings, homes, etc.)		
Street Address Clark & Elmer streets (Block 3 Building 101)			Square Feet # of Floors Bldg. Age 99,999 4 80		
City (5) Trenton	County (6) Mercer	County Code (7) (STATE USE ONLY)	Current Use (Prior if being demolished) library		
Name of Monitoring Firm Hired by Building Owner (8) Environmental Connections Inc		ASCM No.	Name of Abatement Contractor (9) Associated Specialty Contracting Inc		
Street Address 120 North Warren Street			Street Address 98 LaCrue Avenue		
City, State, Zip Code Trenton NJ 08608			City, State, Zip Code Glen Mills, PA 19342		
Project Manager of Monitoring Firm Mike O'Brien		Telephone Number 609-362-4200	Telephone Number 610-364-9622		Licence Number 1103
Scheduled Start Date (10) 02/02/16 <small>Month/Day/Year</small>		Sched. Completion Date (11) 10/31/16 <small>Month/Day/Year</small>		Name of OSHA Monitor Criterion Labs	
Occupancy Status During Abatement (Check only one) <input type="checkbox"/> Facility Closed/Vacated During Entire Period of Abatement <input checked="" type="checkbox"/> Abatement Performed Outside of Normal Facility Hours - Describe: 7:00 AM to 3:30 PM Other - Describe:			Street Address 3370 Progress Dr City, State, Zip Code Bensalem, PA 19020		

Scope of work (Check all that apply)

<input type="checkbox"/> Demolition >3 sf or >3 if	<input checked="" type="checkbox"/> Renovation	<input checked="" type="checkbox"/> Full Containment with Negative Pressure
<input checked="" type="checkbox"/> >160 sf or >260 lf		<input checked="" type="checkbox"/> Mini - Enclosure
		<input checked="" type="checkbox"/> Glovebag Procedure
		<input checked="" type="checkbox"/> Non-Friable Procedure

Location of Asbestos - Containing Material (ACM) TO BE ABATED In Facility (13)	Is Location Normally Used Solely by Main-tenance/ Custodial Staff (12)			Description of Asbestos-Containing Material (ACM) (ie. Thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specifv SF or LF)	Abatement Type			
	Yes	No	N/A			R E M O V A L	R E P A I R	E N C A P S U L	E N C L O S U R E
1st, 2nd, 3rd, 4th fls, & exterior		<input checked="" type="checkbox"/>		glazing	3000 LF	<input checked="" type="checkbox"/>			
Roof		<input checked="" type="checkbox"/>		Roofing material	28325 SF	<input checked="" type="checkbox"/>			
1st fl Mezzaine		<input checked="" type="checkbox"/>		cement board	200 SF	<input checked="" type="checkbox"/>			
see attached sheets									

Name of Registered Waste Hauler Mercer Group International		NJDEP Waste Hauler ID No.	Cubic Yards of Waste 40	Name of Registered Landfill Tulltown Resources Recovery Facility	
City, State 1519 Rev S Howard Woodson Jr Way, trento NJ 08638		Disposal Date As req.		City, State Tullytown PA	
Completed By (Print or Type) Nick Hoag		Title Project Manager		Signature <i>Nick Hoag</i>	Date 7-13-16

ABS-41
JUN 95

Roebling Bldg 110 and 107

Location of ACM	Description of ACM	Amount	Abatement
BLDG 107- roof	roof material	180 SF	Removal
BLDG 107- windows	glazing	20 LF	Removal
BLDG 107 windows	tar	10 SF	Removal
BLDG 110 roof	roof material	180 SF	Removal